

October 29, 2019

Tracking Number 1Z865F5F0194547236

Mr. Mark Gorog PADEP – Bureau of Air Quality Control Southwest Regional Office 400 Waterfront Drive Pittsburgh, PA 15222

Re:

NSPS 0000a Annual Compliance Report

August 2, 2018 - August 2, 2019

ETC Northeast Field Services, LLC - Pike Compressor Facility

Dear Sir:

ETC Northeast Field Services, LLC¹ (ETC) is submitting this letter to meet the annual reporting requirement of New Source Performance Standard 40 CFR 60, Subpart 0000a (NSPS 0000a) for its affected facilities at the Pike Compressor Facility.

The compliance period for the NSPS 0000a reciprocating compressor affected facilities at the Pike Compressor Facility began on August 2, 2018 and ended on August 2, 2019. In accordance with $\S60.5420a(b)$, the annual report is due 90 days after the end of the compliance period (i.e., October 31, 2019).

This annual report covers the compliance period from August 2, 2018 and ended on August 2, 2019.

I. General Information (§60.5420a(b)(1))

(1) The company name and address of the affected facility.

Mailing Address:

6051 Wallace Rd Ext., Suite 300, Wexford, PA 15090

Facility Location:

Pike Compressor Facility, 282 Teets Road, Rochester, PA 15074

(Latitude: 40.74486, Longitude: -80.17000)

(2) An identification of each affected facility being included in the annual report.

The attached reciprocating compressor summary table contains identification of each NSPS 0000a affected facility.

(3) Beginning and ending dates of the reporting period.

This report covers the period from August 2, 2018 and ended on August 2, 2019.

¹ Energy Transfer Partners, L.P. (ETP, ultimate parent company of ETC) acquired the Pike Compressor Station and its associated NSPS OOOO affected facilities in a 2017 transaction which purchased Cardinal PA Midstream, LLC (Cardinal). ETP subsequently changed Cardinal's legal entity name to ETC Northeast Field Services, LLC but retained its Federal Employer Identification Number (FEIN).

(4) Certification by a responsible official of truth, accuracy, and completeness

Certification statement included at closing of this letter.

II. RECIPROCATING COMPRESSORS (§60.5420a(b)(4))

(1) The cumulative number of hours of operation or the number of months since initial startup, since October 15, 2012, or since the previous reciprocating compressor rod packing replacement, whichever is later.

Please refer to the attached reciprocating compressor summary table.

(2) Records of deviations that occurred during the reporting period.

No deviations occurred during the reporting period.

III. PNEUMATIC CONTROLLERS (§60.5420a(b)(5))

 An identification of each pneumatic controller constructed, modified or reconstructed during the reporting period, including the identification information specified in §60.5390(b)(2) or (c)(2).

ETC did not commence construction of any gas-actuated continuous bleed pneumatic controller affected facilities during the reporting period.

(2) If applicable documentation that the use of pneumatic controller affected facilities with a natural gas bleed greater than 6 standard cubic feet per hour are required and the reasons why.

ETC did not commence construction for any gas-actuated continuous bleed pneumatic controllers utilizing the functional need exemption of 40 CFR 60.5390(a) during the reporting period.

(3) Records of deviations that occurred during the reporting period.

No deviations occurred during the reporting period.

Page 3 of 3 October 29, 2019

Should you have any questions or require additional information, please contact Doug Frisco at (570) 505-3700 or Patty Centofanti of Trinity Consultants at (412) 538-8038.

This certification shall state that, based on information and belief formed after reasonable inquiry, the statements and information in the document are true, accurate, and complete.

Sincerely,

Stephen Schuman

Stephen D. Schuman
VP Operations – East Division

Attachments

Office of Air Enforcement & Compliance - NSPS
1650 Arch Street (3AP00), Philadelphia, PA 19103

Tracking Number 1Z865F5F0190205095

List of Affected Facilities \$60.5420a(b)

	Collection of Fugitive Emission Components at a Compressor Station	,
	Group of Equipment Fu within a Co Process Cor Unit ¹	×
Affected Facilities	Storage Tanks	,
Affected	Pneumatic Pump at a Processing Plant	,
	Pneumatic Controller	:
	Reciprocating Pneumatic Pump at a Compressor Controller Processing Plant	×
	Region	PADEP SWRO
	Municipality	New Sewickley Township
	County	Beaver
	State	Pennsyvania
	Longitude	-80.170000
	Latitude	40.744858
	Legal Entity	ETC Northeast Field 40.744858 -80.170000 Services LLC
	Facility Name	Pike Compressor Facility

Notes: 1. Onshore natural gas processing plants submit semiannual reports in accordance with 40 CFR 60.5422a and §60.487a.

Reciprocating Compressor Affected Facilities 860.5420a(b)(4)

			Operations Trackin	Operations Tracking 60.5420a(b)(4)(i)		
Facility Name	Equipment ID	How are you tracking Operations? (Hours or Months)	Actual Time Reported	What is the start date?	What determined start date? (startup, Sept. 18, 2015, or rod packing replacement whichever is later)	Deviations to Report?
Pike Compressor Facility	ENG-005	Hours	13,576	12/28/2017	Rod Packing Change	No Deviations
Pike Compressor Facility	ENG-006	Hours	7,492	10/1/2018	Startup	No Deviations
Pike Compressor Facility	ENG-007	Hours	6,897	10/1/2018	Rod Packing Change	No Deviations
Pike Compressor Facility	ENG-008	Hours	6,847	10/1/2018	Rod Packing Change	No Deviations
Pike Compressor Facility	Footnote 1	In the annual report submitted October 31, 2018, there was a clerical error classifying the "What determnined start date?" of Unit 5 as "Startup". With this report, ETC corrects this reporting element to reflect "Rod Packing Change".	mitted October 31, 201 up". With this report, E	8, there was a clerical en .TC corrects this reporti	rror classifying the "Wha ng element to reflect "Ro	it determnined start od Packing Change".

Units 1-4, flash gas compressors 1-2, and VRU compressor 1 are subject to NSPS 0000. Units 5-8 are subject to NSPS 0000a.

Footnote 2

Pike Compressor Facility

Pnuematic Controller Affected Facilities 860.5420(b)(5) and 860.5420(b)(5)

Or o do dad o trimado da o	Facility Name	State	Location	Make	Model	Month-Year Constructed	Month-Year Replaced
(EPORTING PERIOD 8/2, The station did not com The station did not com	REPORTING PERIOD 8/2/2018 TO 8/2/2019: i) The station did not commence construction of an ii) The station did not commence construction for a	ly gas-actuated continuou	REPORTING PERIOD 8/2/2019: i) The station did not commence construction of any gas-actuated continuous bleed pneumatic controller affected facilities during the reporting period. ii) The station did not commence construction for any gas-actuated continuous bleed pneumatic controllers utilizing the functional need eventation of 40 CFR 60 5390(a) during the reporting need eventation of 40 CFR 60 5390(a) during need	ller affected facilities du	iring the reporting period	40 CFR 60 5390(a) durit	o the renorting neriod
ii) No deviations occurre	iii) No deviations occurred during the reporting period.	riod.					
2							
-							

Attachment C